



















<p>28610-02201 N.A.</p>  <p>743-901</p>	<p>28650-02220 15.013</p>  <p>743-901 x2</p>	<p>28700-02220 15.012</p>  <p>550-902 743-901</p>	<p>Atos Hatchback 1.0i 02/98 - 03/02 (999 cc), 40 KW</p> <p>HY150300</p> <p>CAT</p>
<p>28520-02820 N.A.</p>  <p>890-908</p>	<p>28610-1C020 15.009</p>  <p>773-903 931-953 773-903 x2</p>	<p>28700-1C060 15.015</p>  <p>773-903</p>	<p>Getz Hatchback 1.1i - 12V 09/02 - 09/05 (1086 cc), 46 KW</p> <p>HY150700</p> <p>CAT</p>
<p>28520-02820 N.A.</p>  <p>890-908</p>	<p>28610-1C510 N.A.</p>  <p>773-903 x2</p>	<p>28700-1C710 N.A.</p>  <p>773-903</p>	<p>Getz Hatchback 1.1i - 12V 09/05 - (1086 cc), 49 KW</p> <p>HY150702</p> <p>CAT</p>
<p>28510-22670 N.A.</p>  <p>890-908</p>	<p>28610-1C060 15.017</p>  <p>773-903 931-953 773-903 x2</p>	<p>28700-1C060 15.015</p>  <p>773-903</p>	<p>Getz Hatchback 1.3i - 12V 09/02 - 09/05 (1341 cc), 60 KW (1341 cc), 63 KW</p> <p>HY150710</p> <p>CAT</p>
<p>28510-26230 N.A.</p>  <p>890-908</p>	<p>28610-1C580 N.A.</p>  <p>773-903 x2</p>	<p>28700-1C710 N.A.</p>  <p>773-903</p>	<p>Getz Hatchback 1.4i - 16V 08/05 - (1399 cc), 71 KW</p> <p>HY150720</p> <p>CAT</p>

550-902  Atos (12/97-)

890-908  Accent (11/99-08/02), Excel (11/99-08/00),
Getz (05/02-), Pony (10/86-08/89)

743-901  Accent (09/94-08/02), Atos (12/97-),
Excel (10/89-08/00), Pony (01/86-10/99),
Sonata (07/93-04/98)

773-903  Excel (10/89-06/94), Getz (05/02-), Pony (08/89-
12/92)

931-953  Getz (05/02-)

15.009 773-903, 773-903 2x, 890-908

15.012 550-902, 743-901

15.013 550-902, 743-901 2x

15.015 773-903, 931-953

15.016 773-903 2x, 890-908

15.017 773-903, 773-903 2x, 931-953
